

General Environmental Incident Summary

Incident: 2152 **Date/Time Notice:** 12/24/2013 0802 **DEM Incident No:**

Responsible Party: Missouri Basin Well Service, Inc

Date Incident: 12/24/2013 **Time Incident:** 1930 **Duration:**

County: Mountrail **Twp:** 156 **Rng:** 93 **Sec:** 23 **Qtr:**

Lat: 48.31743 **Long:** -102.59390 **Method:** Navigation quality GPS

Location Description: 6225 91st Ave NW, Ross ND 58776

Submitted By: Tara DeJoseph

Affiliation:

Address: PO BOX 458

City: Belfield

State: ND

Zip:

Received By:

Contact Person:

PO BOX 458

Belfield, ND

Distance Nearest Occupied Building:

Type of Incident: Tank Overflow

Description of Released Contaminant: Salt water

Volume Spilled: 10.00 barrels

Ag Related: No

EPA Extremely Hazardous Substance: Unknown

Reported to NRC: Unknown

Cause of Incident:

Ice thawed out in tank and spilled out hatch

Risk Evaluation:

N/a

of Fatalities: 0

of Injuries: 0

Affected Medium:

Potential Environmental Impacts:

N/a

Action Taken or Planned:

Vac truck cleaned up standing water, bobcat scrapped up contaminated soil

Wastes Disposal Location: Ross ND MBI yard

Agencies Involved:

Updates

Date: 12/24/2013 **Status:** Reviewed - Follow-up Required

Author: Stockdill, Scott

Updated Volume:

Notes:

Followup necessary to confirm proper cleanup and disposal of impacted materials. Followup scheduled by Scott Stockdill on Thursday, December 26, 2013.

Date: 1/2/2014 **Status:** Inspection

Author: Miller, Adam

Updated Volume:

Notes:

Soil has been scraped up and placed in container on location; awaiting disposal. The spill was on the MBI Ross Yard, near the NW corner. Company personnel showed me where the spill occurred.